Certified Automotive Parts Association
Washington, DC

NOTICE OF STATUS (PART NUMBER/PART LOT) CHANGE FORM

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	29738
Notification Date / 通知日期:	03/16/2017
Participant Name / 廠商名稱:	Gordon Auto Body Parts Co., Ltd.
Participant Address / 廠商地址:	No. 48, Neixi Road, Luzhu District, Taoyuan City 338

Applicable CAPA Certification Standard / 適用之CAPA認證標準:	[X] CAPA 101	[ ] CAPA 201	[ ] CAPA 301	[ ] CAPA 501	[ ] CAPA 601

Participant Part Number / 零件號碼:	ADA315FL1		
Car Company Part Number / CCS 號碼:	8V5821105A	Partslink Number / 號碼:	AU1240136
Part Description / 零件種類:	Fender L		
Application Description / 車種年份:	Audi A3 Cabrio, 15-16 Audi A3 Sedan, 15-16 Audi S3 Sedan, 15-16		

Status Affects / 受影響狀態:	[X] Part Number / 零件編號	[X] Lot Number / 批號: 03/17A

Status as of this Notice / 通知後狀態: **NEW PART APPROVAL**

Reason for Status Change / 狀態變更原因:	[ ] Participant Request / 廠商要求	[ ] Production Inspection 產品檢驗	[ ] CAR / 改善措施要求
[ ] Random Material Testing 隨機抽樣材測	[ ] MM VTF / 市場觀察合車	[X] Other / 其他:	

Describe / 原因: NPA – passed dimension test.

Seal Size: / 標籤尺寸: [X] Standard / 標準 [ ] Alternative / 替代選擇

When a part number is decertified or deleted, in order to re-enter the CAPA Certification Program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval Fee.

註 ：當整個零件號碼被取消認證或刪除時, 如欲將該零件重新加入CAPA認證計畫, 廠商必須送交新零件註冊登記表為零件重新註冊, 並繳交新零件核可費用。

Submitted By / 提案人:		Issued By / 簽發者:	
	CAPA Validator		CAPA Administrator

© 2017 CAPA