Certified Automotive Parts Association
Washington, DC

NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	18138
Notification Date / 通知日期:	08/30/2012
Participant Name / 廠商名稱:	Tong Yang Industry Co., Ltd
Participant Address / 廠商地址:	No. 98, Sec. 2, An Ho Road Tainan R.O.C., 709

Applicable CAPA Certification Standard / 適用之CAPA認證標準:	[X] CAPA 101	[ ] CAPA 201	[ ] CAPA 301	[ ] CAPA 501	[ ] CAPA 201A	[ ] CAPA 401

Participant Part Number / 零件號碼:	VW-20052AQ		
Car Company Part Number / CCS 號碼:	5C6823031C	Partslink Number / 號碼:	VW1230142
Part Description / 零件種類:	Hood		
Application Description / 車種年份:	Volkwagen Jetta Sedan, 11-12		

Status Affects / 受影響狀態:	[X] Part Number / 零件編號	[X] Lot Number / 批號: 08/12A

Status as of this Notice / 通知後狀

NEW PART APPROVAL

Reason for Status Change / 狀態變更原	[ ] Participant Request / 廠商要求	[ ] Production Inspection 產品檢驗	[ ] CAR / 改善措施要求
[ ] Random Material Testing 隨機抽樣材測	[ ] MM VTF / 市場觀察合車	[X] Other / 其他:	

Describe / 原因: NPA - passed dimension test and closed out CAR # 12-0553.

Seal Size: / 標籤尺寸: [X] Standard / 標準 [ ] Alternative / 替代選擇

NOTE: When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee.

註 ：當整個零件號碼被取消認證或刪除時, 如欲將該零件重新加入CAPA認證計畫, 廠商必須送交新零件註冊登記表爲零件重新註冊, 並繳交新零件核可費用。

Submitted By / 提案人:	James Chen	Issued By / 簽發者:	
	CAPA Validator		CAPA Administrator

© 2012 CAPA