




NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	15097						
Notification Date / 通知日期:	10/20/2010						
Participant Name / 廠商名稱:	Tong Yang Industry Co., Ltd						
Participant Address / 廠商地址:	No. 98, Sec. 2, An Ho Road Tainan R.O.C., 709						
Applicable CAPA Certification Standard / 適用之CAPA認證標準:	☒ CAPA 101 ☐ CAPA 201 ☐ CAPA 301 ☐ CAPA 401						
Participant Part Number / 零件號碼:	AD-10023AQ-LH						
Car Company Part Number / CCS 號碼:	8K0821105A			Partslink Number / 號碼:	AU1241121		
Part Description / 零件種類:	Fender L						
Application Description / 車種年份:	Make/ 車種:	Audi	Model/ 車型:	A4	Years/ 年份:	09-10	
	Make/ 車種:		Model/ 車型:		Years/ 年份:		
	Make/ 車種:		Model/ 車型:		Years/ 年份:		
Status Affects / 受影響狀態:	☒ Part Number / 零件編號		☒ Lot Number / 批號:		10/10A		
Status as of this Notice / 通知後狀態:	NEW PART APPROVAL						
Reason for Status Change / 狀態變更原因:	☐ Participant Request / 廠商要求		☐ Production Inspection 產品檢驗		☐ CAR / 改善措施要求		
☐ Random Material Testing 隨機抽樣材測	☐ MM VTF / 市場觀察合車		☒ Other / 其他:				
Describe / 原因: <u>NPA - passed dimension test.</u>							
Seal Size: / 標籤尺寸:	☒ Standard / 標準		☐ Alternative / 替代選擇				
NOTE: When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee. 註： 當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。							
Submitted By / 提案人:				Issued By / 簽發者:			
	CAPA Validator				CAPA Administrator		