

NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:		19943	
Notification Date / 通知日期:		07/31/2013	
Participant Name / 廠商名稱:		Tong Yang Industry Co., Ltd/Chang Jung	
Participant Address / 廠商地址:		No. 98, Sec. 2, An Ho Road Tainan R.O.C., 709	
Applicable CAPA Certification Standard / 適用之CAPA認證標準:		☒ CAPA 101 ☐ CAPA 201 ☐ CAPA 301 ☐ CAPA 501 ☐ CAPA 201A ☐ CAPA 401	
Participant Part Number / 零件號碼:		HD-10109AQ-LH/CR-508A-LH	
Car Company Part Number / CCS 號碼:		60261SWAA91ZZ	Partslink Number / 號碼: HO1240171
Part Description / 零件種類:		Fender L	
Application Description / 車種年份:		Honda CR-V, 07-11	
Status Affects / 受影響狀態:		☒ Part Number / 零件編號	☐ Lot Number / 批號: ALL
Status as of this Notice / 通知後狀態:		NEW PART APPROVAL	
Reason for Status Change / 狀態變更原因:		☒ Participant Request / 廠商要求	☐ Production Inspection 產品檢驗
☐ Random Material Testing 隨機抽樣材測		☐ MM VTF / 市場觀察合車	☐ CAR / 改善措施要求
Describe / 原因: <u>New shared tool relationship with Chang Jung</u>		☐ Other / 其他:	
Seal Size: / 標籤尺寸:		☒ Standard / 標準	☐ Alternative / 替代選擇
NOTE: When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee. 註：當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。			
Submitted By / 提案人:		Issued By / 簽發者:	
CAPA Validator		CAPA Administrator	