

NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:		23858	
Notification Date / 通知日期:		02/13/2015	
Participant Name / 廠商名稱:		Tong Yang Industry Co., Ltd	
Participant Address / 廠商地址:		No. 98, Sec. 2, An Ho Road, Annan District Tainan R.O.C., 709	
Applicable CAPA Certification Standard / 適用之CAPA認證標準:		☐ CAPA 101 ☒ CAPA 201 ☐ CAPA 301 ☐ CAPA 501 ☐ CAPA 201A ☐ CAPA 401	
Participant Part Number / 零件號碼:		MZ-04153BBQ	
Car Company Part Number / CCS 號碼:		KDY75022XDBB	Partslink Number / 號碼: MA1100217
Part Description / 零件種類:		Bumper Cover, Rear	
Application Description / 車種年份:		Mazda CX-5, 13-15	
Status Affects / 受影響狀態:		☒ Part Number / 零件編號	☒ Lot Number / 批號: 12/14A
Status as of this Notice / 通知後狀態:		NEW PART APPROVAL	
Reason for Status Change / 狀態變更原因:		☐ Participant Request / 廠商要求	☐ Production Inspection 產品檢驗
☐ Random Material Testing 隨機抽樣材測		☐ MM VTF / 市場觀察合車	☒ Other / 其他:
Describe / 原因: <u>Passed all testing requirements.</u>			
Seal Size: / 標籤尺寸:		☒ Standard / 標準	☐ Alternative / 替代選擇
NOTE: When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee. 註: 當整個零件號碼被取消認證或刪除時, 如欲將該零件重新加入CAPA認證計畫, 廠商必須送交新零件註冊登記表為零件重新註冊, 並繳交新零件核可費用。			
Submitted By / 提案人:		Issued By / 簽發者:	
			
CAPA Validator		CAPA Administrator	