

NOTICE OF STATUS (PART NUMBER/PART LOT) CHANGE FORM

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	47571
Notification Date / 通知日期:	08/31/2021
Participant Name / 廠商名稱:	Tong Yang Industry Co., Ltd
Participant Address / 廠商地址:	No. 98, Sec. 2, An Ho Road, Annan District, Tainan 709
Participant Part Number / 零件號碼:	KA-04149BDQ
(CCS) Part Number / 原廠零件編號:	86611G5010
Partslink Number / 號碼:	KI1114110
Part Description / 零件種類:	Bumper Cover, Rear
Application Description / 車種年份:	Kia Niro w/Parking Sensors, 17 - 19

Applicable CAPA Certification Standard 201 Plastics
/ 適用之CAPA認證標準:

Status Affects / 受影響狀態: ☒ Part Number / 零件編號 ☒ Lot Number / 批號: 08/21A

Status as of this Notice / 通知後狀態:

NEW PART APPROVAL

Reason for Status Change:
狀態變更原因:

☐ Participant Request / 廠商要求	☐ Production Inspection 產品檢驗	☐ CAR / 改善措施要求
☐ Random Material Testing 隨機抽樣材測	☐ MM VTF / 市場觀察合車	
☒ Other - Describe: NPA – passed dimension test. 其他 - 請詳述:		

When a part number is decertified or deleted, in order to re-enter the CAPA Certification Program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval Fee.

註：當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。

Internal Use Only / 僅供內部使用

Submitted By / 提案人

Issued By / 簽發者


