

NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	18097		
Notification Date / 通知日期:	08/23/2012		
Participant Name / 廠商名稱:	Gordon Auto Body Parts Co., Ltd.		
Participant Address / 廠商地址:	No. 48, Nie-Shi Road Lu Chu Hsiang Taoyuan County R.O.C., 338		
Applicable CAPA Certification Standard / 適用之CAPA認證標準:	<input checked="" type="checkbox"/> CAPA 101 <input type="checkbox"/> CAPA 201 <input type="checkbox"/> CAPA 301 <input type="checkbox"/> CAPA 501 <input type="checkbox"/> CAPA 201A <input type="checkbox"/> CAPA 401		
Participant Part Number / 零件號碼:	BKR10HD1		
Car Company Part Number / CCS 號碼:	20989165	Partslink Number / 號碼:	GM1230396
Part Description / 零件種類:	Hood		
Application Description / 車種年份:	Buick Regal, 11		
Status Affects / 受影響狀態: <input checked="" type="checkbox"/> Part Number / 零件編號 <input checked="" type="checkbox"/> Lot Number / 批號: 08/12A			
Status as of this Notice / 通知後狀		NEW PART APPROVAL	
Reason for Status Change / 狀態變更原因	<input type="checkbox"/> Participant Request / 廠商要求	<input type="checkbox"/> Production Inspection 產品檢驗	<input type="checkbox"/> CAR / 改善措施要求
<input type="checkbox"/> Random Material Testing 隨機抽樣材測	<input type="checkbox"/> MM VTF / 市場觀察合車	<input checked="" type="checkbox"/> Other / 其他:	
Describe / 原因: <u>NPA - passed dimension test and closed out CAR # 12-1465 and 12-1279.</u>			
Seal Size: / 標籤尺寸:	<input checked="" type="checkbox"/> Standard / 標準		<input type="checkbox"/> Alternative / 替代選擇
NOTE: When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee. 註： 當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。			
Submitted By / 提案人:			Issued By / 簽發者:
	CAPA Validator		CAPA Administrator