


NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:		16437					
Notification Date / 通知日期:		09/14/2011					
Participant Name / 廠商名稱:		Tong Yang Industry Co., Ltd					
Participant Address / 廠商地址:		No. 98, Sec. 2, An Ho Road Tainan R.O.C., 709					
Applicable CAPA Certification Standard / 適用之CAPA認證標準:		☒ CAPA 101	☐ CAPA 201	☐ CAPA 301	☐ CAPA 501	☐ CAPA 201A	☐ CAPA 401
Participant Part Number / 零件號碼:		MZ-20052AQ					
Car Company Part Number / CCS 號碼:		D6Y15231X			Partslink Number / 號碼:		MA1230168
Part Description / 零件種類:		Hood					
Application Description / 車種年份:	Make/ 車種:	Mazda	Model/ 車型:	2	Years/ 年份:	11-11	
	Make/ 車種:		Model/ 車型:		Years/ 年份:		
	Make/ 車種:		Model/ 車型:		Years/ 年份:		
Status Affects / 受影響狀態:		☒ Part Number / 零件編號	☒ Lot Number / 批號: 06/11A				
Status as of this Notice / 通知後狀態:		NEW PART APPROVAL					
Reason for Status Change / 狀態變更原因:		☐ Participant Request / 廠商要求		☐ Production Inspection 產品檢驗		☐ CAR / 改善措施要求	
☐ Random Material Testing 隨機抽樣材測		☐ MM VTF / 市場觀察合車		☒ Other / 其他:			
Describe / 原因: <u>NPA - passed dimension test.</u>							
Seal Size: / 標籤尺寸:		☒ Standard / 標準		☐ Alternative / 替代選擇			
NOTE: When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee. 註：當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。							
Submitted By / 提案人:				Issued By / 簽發者:			
		CAPA Validator				CAPA Administrator	