

NOTICE OF STATUS (PART NUMBER/PART LOT) CHANGE FORM

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	35266
Notification Date / 通知日期:	11/12/2018
Participant Name / 廠商名稱:	Tong Yang Industry Co., Ltd
Participant Address / 廠商地址:	No. 98, Sec. 2, An Ho Road, Annan District, Tainan 709
Participant Part Number / 零件號碼:	TY-04558BCQ
Car Company Service (CCS) Part Number 原廠零件編號:	5215942930
Partlink Number / 號碼:	TO1114103
Part Description / 零件種類:	Bumper Cover, Rear
Application Description / 車種年份:	Toyota RAV-4, 16-18, Hybrid

Note: Even though one application is identified on this form, if the part is used on multiple applications, all applications will apply.

備註: 廠商必須在本表上註明至少一種車種, 但如果零件可用於多個車種, 則所有車種都會列入註冊。

Applicable CAPA Certification Standard 201 Plastics
/ 適用之CAPA認證標準:

Status Affects / 受影響狀態: ☒ Part Number / 零件編號 ☒ Lot Number / 批號: 11/18A

Status as of this Notice / 通知後狀態:

NEW PART APPROVAL

Reason for Status Change:
狀態變更原因:

<input type="checkbox"/> Participant Request / 廠商要求	<input type="checkbox"/> Production Inspection 產品檢驗	<input type="checkbox"/> CAR / 改善措施要求
<input type="checkbox"/> Random Material Testing 隨機抽樣材測	<input type="checkbox"/> MM VTF / 市場觀察合車	
<input checked="" type="checkbox"/> Other - Describe: NPA – passed dimension test. 其他 - 請詳述:		

When a part number is decertified or deleted, in order to re-enter the CAPA Certification Program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval Fee.

註: 當整個零件號碼被取消認證或刪除時, 如欲將該零件重新加入CAPA認證計畫, 廠商必須送交新零件註冊登記表為零件重新註冊, 並繳交新零件核可費用。

Internal Use Only / 僅供內部使用

Submitted By / 提案人

Issued By / 簽發者

Brian Huang

Jillian Rahal