




Certified Automotive Parts Association
Washington, DC

NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	13906					
Notification Date / 通知日期:	01/19/2010					
Participant Name / 廠商名稱:	Taiwan Kai Yih Industrial Co., Ltd.					
Participant Address / 廠商地址:	No. 202, Lane 250, Jian-An Road Tainan City R.O.C.. 709					
Applicable CAPA Certification Standard / 適用之CAPA認證標準:	☒ CAPA 101 ☐ CAPA 201 ☐ CAPA 301 ☐ CAPA 401					
Participant Part Number / 零件號碼:	BM-10021AQ-RH					
Car Company Part Number / CCS 號碼:	41357111430	Partslink Number / 號碼:	BM1241130			
Part Description / 零件種類:	Fender R					
Application Description / 車種年份:	Make/ 車種:	BMW	Model/ 車型:	5-Series	Years/ 年份:	04-09
	Make/ 車種:		Model/ 車型:		Years/ 年份:	
	Make/ 車種:		Model/ 車型:		Years/ 年份:	
Status Affects / 受影響狀態:	☒ Part Number / 零件編號		☒ Lot Number / 批號: 01/10A			
Status as of this Notice / 通知後狀態:	NEW PART APPROVAL					
Reason for Status Change / 狀態變更原因:	☐ Participant Request / 廠商要求		☐ Production Inspection 產品檢驗		☐ CAR / 改善措施要求	
☐ Random Material Testing 隨機抽樣材測	☐ MM VTF / 市場觀察合車		☒ Other / 其他:			
Describe / 原因: <u>NPA - passed dimension test.</u>						
Seal Size: / 標籤尺寸:	☒ Standard / 標準		☐ Alternative / 替代選擇			
NOTE: When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee. 註：當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。						
Submitted By / 提案人:			Issued By / 簽發者:			
	CAPA Validator			CAPA Administrator		