



NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	15997					
Notification Date / 通知日期:	06/02/2011					
Participant Name / 廠商名稱:	Tong Yang Industry Co., Ltd					
Participant Address / 廠商地址:	No. 98, Sec. 2, An Ho Road Tainan R.O.C., 709					
Applicable CAPA Certification Standard / 適用之CAPA認證標準:	<input checked="" type="checkbox"/> CAPA 101 <input type="checkbox"/> CAPA 201 <input type="checkbox"/> CAPA 301 <input type="checkbox"/> CAPA 401 <input type="checkbox"/> CAPA 501					
Participant Part Number / 零件號碼:	AD-10017CQ-LH					
Car Company Part Number / CCS 號碼:	4F0821103F	Partslink Number / 號碼:	AU1240123			
Part Description / 零件種類:	Fender L					
Application Description / 車種年份:	Make/ 車種:	Audi	Model/ 車型:	A6	Years/ 年份:	09-10
	Make/ 車種:		Model/ 車型:		Years/ 年份:	
	Make/ 車種:		Model/ 車型:		Years/ 年份:	
Status Affects / 受影響狀態:	<input checked="" type="checkbox"/>	Part Number / 零件編號	<input checked="" type="checkbox"/>	Lot Number / 批號:	05/11A	
Status as of this Notice / 通知後狀態:	NEW PART APPROVAL					
Reason for Status Change / 狀態變更原因:	<input type="checkbox"/>	Participant Request / 廠商要求	<input type="checkbox"/>	Production Inspection 產品檢驗	<input type="checkbox"/>	CAR / 改善措施要求
<input type="checkbox"/> Random Material Testing 隨機抽樣材測	<input type="checkbox"/>	MM VTF / 市場觀察合車	<input checked="" type="checkbox"/>	Other / 其他:		
Describe / 原因: <u>NPA - passed dimension test.</u>						
Seal Size: / 標籤尺寸:	<input checked="" type="checkbox"/>	Standard / 標準	<input type="checkbox"/>	Alternative / 替代選擇		
<p>NOTE: When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee.</p> <p>註：當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。</p>						
Submitted By / 提案人:			Issued By / 簽發者:			
	CAPA Validator			CAPA Administrator		