


Skoda Octavia 13- Original Vehicle Before Assessment



Skoda Octavia 13- Under Bonnet Cross Dimensional Measurement



X


Y

"X" Measures a distance of: 1571mm


"Y" Measures a distance of: 1571mm

Vehicle Within Required Tolerance


Skoda Octavia 13- Original Bonnet Gaps




Skoda Octavia 13- Tong Yang Bonnet Gaps




TYG Bonnet L/H




Original Bonnet L/H




Skoda Octavia 13-




TYG Bonnet L/H



Original Bonnet R/H





Skoda Octavia 13-






Original Bonnet R/H

Skoda Octavia 13-




Original Bonnet R/H


TYG Bonnet L/H




Original Bonnet L/H



Skoda Octavia 13-




TYG Bonnet R/H




Original Bonnet R/H

TYG Bonnet R/H




Inner bonnet strengthening panel not correctly fitting under folded outer edge of the bonnet.

TYG Bonnet R/H




Skoda Octavia 13-




No seam sealer around bonnet edge.

TYG Bonnet R/H




TYG Bonnet R/H

TYG Bonnet Centre




Adhesive not correctly stuck

TYG Bonnet L/H Front




Adhesive not correctly stuck
due to bad fitting

Skoda Octavia 13-



Incorrect fitting of inner panel,
adhesive spread across
bonnet and not enough to
bond the two panels together



TYG Bonnet




TYG Bonnet L/H

Skoda Octavia 13-

- Faults Identified
- Comparative Fit Quality To Original
- Slide 10 - Inner bonnet strengthening panel not correctly fitting under folded outer edge of the bonnet.
- Slide 11 - Incorrect fitting of inner panel, adhesive spread across bonnet and not enough to bond the two panels together
- VTF Judgement: **Failed**



Skoda Octavia 13-



Skoda Octavia 13-

- Slide 13 – Shows all corrective actions have been addressed
- VTF Judgement: Pass