


NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE

CAPA 零件號碼 / 批號狀態變更通知

| | | | | | | | |
|--|--|---|---|---|---|------------------------------------|---|
| Notification Number / 通知單編號: | | 17018 | | | | | |
| Notification Date / 通知日期: | | 01/19/2012 | | | | | |
| Participant Name / 廠商名稱: | | Gordon Auto Body Parts Co., Ltd. | | | | | |
| Participant Address / 廠商地址: | | No. 48, Nie-Shi Road Lu Chu Hsiang Taoyuan County R.O.C., 338 | | | | | |
| Applicable CAPA Certification Standard / 適用之CAPA認證標準: | | <input checked="" type="checkbox"/> CAPA 101 | <input type="checkbox"/> CAPA 201 | <input type="checkbox"/> CAPA 301 | <input type="checkbox"/> CAPA 501 | <input type="checkbox"/> CAPA 201A | <input type="checkbox"/> CAPA 401 |
| Participant Part Number / 零件號碼: | | ADA309FR1 | | | | | |
| Car Company Part Number / CCS 號碼: | | | 8P0821106G | | Partslink Number / 號碼: | | AU1241120 |
| Part Description / 零件種類: | | Fender R | | | | | |
| Application Description / 車種年份: | | Make/ 車種: | Audi | Model/ 車型: | A3 | Years/ 年份: | 06-11 |
| | | Make/ 車種: | | Model/ 車型: | | Years/ 年份: | |
| | | Make/ 車種: | | Model/ 車型: | | Years/ 年份: | |
| Status Affects / 受影響狀態: | | <input checked="" type="checkbox"/> Part Number / 零件編號 | <input checked="" type="checkbox"/> Lot Number / 批號: 01/12A | | | | |
| Status as of this Notice / 通知後狀態: | | NEW PART APPROVAL | | | | | |
| Reason for Status Change / 狀態變更原因: | | <input type="checkbox"/> Participant Request / 廠商要求 | <input type="checkbox"/> Production Inspection / 產品檢驗 | | <input type="checkbox"/> CAR / 改善措施要求 | | |
| <input type="checkbox"/> Random Material Testing / 隨機抽樣材測 | | <input type="checkbox"/> MM VTF / 市場觀察合車 | | <input checked="" type="checkbox"/> Other / 其他: | | | |
| Describe / 原因: <u>NPA - passed dimension test.</u> | | | | | | | |
| Seal Size: / 標籤尺寸: | | <input checked="" type="checkbox"/> Standard / 標準 | | | <input type="checkbox"/> Alternative / 替代選擇 | | |
| <p>NOTE: When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee.</p> <p>註：當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。</p> | | | | | | | |
| Submitted By / 提案人: | |  | | | Issued By / 簽發者: | |  |
| | | CAPA Validator | | | CAPA Administrator | | |