


NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	18100		
Notification Date / 通知日期:	08/23/2012		
Participant Name / 廠商名稱:	Tong Yang Industry Co., Ltd		
Participant Address / 廠商地址:	No. 98, Sec. 2, An Ho Road Tainan R.O.C., 709		
Applicable CAPA Certification Standard / 適用之CAPA認證標準:	☒ CAPA 101	☐ CAPA 201	☐ CAPA 301
	☐ CAPA 501	☐ CAPA 201A	☐ CAPA 401
Participant Part Number / 零件號碼:	BZ-10064AQ-RH		
Car Company Part Number / CCS 號碼:	2128800218	Partslink Number / 號碼:	MB1241134
Part Description / 零件種類:	Fender R		
Application Description / 車種年份:	Mercedes-Benz E Class Sedan, 10-11, E350 / E550		
	Mercedes-Benz E Class Wagon, 11		
Status Affects / 受影響狀態:	☒ Part Number / 零件編號	☒ Lot Number / 批號:	08/12A
Status as of this Notice / 通知後狀	NEW PART APPROVAL		
Reason for Status Change / 狀態變更原因	☐ Participant Request / 廠商要求	☐ Production Inspection 產品檢驗	☐ CAR / 改善措施要求
☐ Random Material Testing 隨機抽樣材測	☐ MM VTF / 市場觀察合車	☒ Other / 其他:	
Describe / 原因: <u>NPA - passed dimension test.</u>			
Seal Size: / 標籤尺寸:	☒ Standard / 標準	☐ Alternative / 替代選擇	
NOTE: When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee. 註：當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。			
Submitted By / 提案人:		Issued By / 簽發者:	
	CAPA Validator		CAPA Administrator