




NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	11167				
Notification Date / 通知日期:	04/23/2008				
Participant Name / 廠商名稱:	Tong Yang Industry Co., Ltd.				
Participant Address / 廠商地址:	No. 98, Sec. 2, An Ho Road Tainan R.O.C., 709				
Applicable CAPA Certification Standard / 適用之CAPA認證標準:	☐ CAPA 101 ☒ CAPA 201 ☐ CAPA 301 ☐ CAPA 401				
Participant Part Number / 零件號碼:	HD-04168BAQ				
Car Company Part Number / CCS 號碼:	04715SWAA90		Partslink Number / 號碼:		
Part Description / 零件種類:	Bumper Cover, Rear				
Application Description / 車種年份:	Make/ 車種:	Honda	Model/ 車型:	CR-V	Years/ 年份: 07-08
	Make/ 車種:		Model/ 車型:		Years/ 年份:
	Make/ 車種:		Model/ 車型:		Years/ 年份:
Status Affects / 受影響狀態:	☒ Part Number / 零件編號		☒ Lot Number / 批號: 03/08A		
Status as of this Notice / 通知後狀態:	NEW PART APPROVAL				
Reason for Status Change / 狀態變更原因:	☐ Participant Request / 廠商要求		☐ Production Inspection 產品檢驗		☐ CAR / 改善措施要求
☐ Random Material Testing 隨機抽樣材測	☐ MM VTF / 市場觀察合車		☒ Other / 其他:		
Describe / 原因: <u>Passed all testing requirements</u>					
Part number decertification or deletion. To re-enter the CAPA program the following testing will be required / 零件號碼取消認證或刪除 要重回CAPA計劃必須完成以下的測試:					
☐	Complete Part Testing (including Confirmation of Material Usage Form or hood striker area material testing, Dimensional, Appearance and QC Record Inspections, Checking, Assembly and Staging Fixture Approval, 30 pc. Capability Study, NPA VTF B) / 完成新零件測試 (包括: 材質同意書, 若為引擎蓋則增加安全鎖扣區域材質測試, 尺寸/外觀/O.C.報告檢驗, 檢具/組立治具/工作架檢具核可, 30片製程能力分析, 合車測試 VTF B)				
☐	Full Material Test / 所有材質測試				
☐	AM Part(s) Only / 僅 AM件		☐ :CS and AM Part(s) / CCS及AM 件		
Submitted By / 提案人:			Issued By / 簽發者:		
	CAPA Validator			CAPA Administrator	