


NOTICE OF STATUS (PART NUMBER/PART LOT) CHANGE FORM

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	31844		
Notification Date / 通知日期:	11/17/2017		
Participant Name / 廠商名稱:	Gordon Auto Body Parts Co., Ltd.		
Participant Address / 廠商地址:	No. 48, Neixi Road, Luzhu District, Taoyuan City 338		
Participant Part Number / 零件號碼:	VWTG17FL1		
Car Company Service (CCS) Part Number 原廠零件編號:	5NA821105		
Partslink Number / 號碼:	VW1240150		
Part Description / 零件種類:	Fender L		
Application Description / 車種年份:	Volkswagen Tiguan, 18		
<p>Note: Even though one application is identified on this form, if the part is used on multiple applications, all applications will apply. 備註: 廠商必須在本表上註明至少一種車種, 但如果零件可用於多個車種, 則所有車種都會列入註冊。</p>			
Applicable CAPA Certification Standard / 適用之CAPA認證標準:	101 Metals		
Status Affects / 受影響狀態:	<input checked="" type="checkbox"/> Part Number / 零件編號	<input checked="" type="checkbox"/> Lot Number / 批號:	11/17A
Status as of this Notice / 通知後狀態:	NEW PART APPROVAL		
Reason for Status Change: 狀態變更原因:	<input type="checkbox"/> Participant Request / 廠商要求	<input type="checkbox"/> Production Inspection 產品檢驗	<input type="checkbox"/> CAR / 改善措施要求
	<input type="checkbox"/> Random Material Testing 隨機抽樣材測	<input type="checkbox"/> MM VTF / 市場觀察合車	
	<input checked="" type="checkbox"/> Other - Describe: NPA – passed dimension test. 其他 - 請詳述:		
<p>When a part number is decertified or deleted, in order to re-enter the CAPA Certification Program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval Fee. 註: 當整個零件號碼被取消認證或刪除時, 如欲將該零件重新加入CAPA認證計畫, 廠商必須送交新零件註冊登記表為零件重新註冊, 並繳交新零件核可費用。</p>			
CAPA Validator Use Only / 僅供CAPA 驗證機構使用			
Submitted By / 提案人:		Issued By / 簽發者:	
CAPA Validator Signature: CAPA 驗證機構簽名:		CAPA Administrator Signature: CAPA 行政人員簽名:	