


NOTICE OF STATUS (PART NUMBER/PART LOT) CHANGE FORM

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	31916		
Notification Date / 通知日期:	11/27/2017		
Participant Name / 廠商名稱:	Tong Yang Industry Co., Ltd		
Participant Address / 廠商地址:	No. 98, Sec. 2, An Ho Road, Annan District, Tainan 709		
Participant Part Number / 零件號碼:	AD-07046GAQ		
Car Company Service (CCS) Part Number 原廠零件編號:	8W08076839B9		
Partslink Number / 號碼:	AU1036110		
Part Description / 零件種類:	Grille, Lower		
Application Description / 車種年份:	Audi A4, 16-18, w/o S-Line Pkg		
Note: Even though one application is identified on this form, if the part is used on multiple applications, all applications will apply. 備註: 廠商必須在本表上註明至少一種車種, 但如果零件可用於多個車種, 則所有車種都會列入註冊。			
Applicable CAPA Certification Standard / 適用之CAPA認證標準:	201 Plastics		
Status Affects / 受影響狀態:	☒ Part Number / 零件編號	☒ Lot Number / 批號:	11/17A
Status as of this Notice / 通知後狀態:	NEW PART APPROVAL		
Reason for Status Change: 狀態變更原因:	☐ Participant Request / 廠商要求	☐ Production Inspection 產品檢驗	☐ CAR / 改善措施要求
	☐ Random Material Testing 隨機抽樣材測	☐ MM VTF / 市場觀察合車	
	☒ Other - Describe: NPA – passed dimension test. 其他 - 請詳述:		
When a part number is decertified or deleted, in order to re-enter the CAPA Certification Program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval Fee. 註：當整個零件號碼被取消認證或刪除時, 如欲將該零件重新加入CAPA認證計畫, 廠商必須送交新零件註冊登記表為零件重新註冊, 並繳交新零件核可費用。			
CAPA Validator Use Only / 僅供CAPA 驗證機構使用			
Submitted By / 提案人:		Issued By / 簽發者:	
CAPA Validator Signature: CAPA 驗證機構簽名:		CAPA Administrator Signature: CAPA 行政人員簽名:	