

Skoda Fabia 10- Original Vehicle Before Assessment



Skoda Fabia 10- Original Centre Grille



Skoda Fabia 10- TONG YANG Centre Grille





Skoda Fabia 10-



Skoda Fabia 10-

- No Faults Identified
- Comparative Fit Quality To Original
- VTF Judgement: **PASS**