



NOTICE OF STATUS (PART NUMBER/PART LOT) CHANGE FORM

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	29925				
Notification Date / 通知日期:	04/10/2017				
Participant Name / 廠商名稱:	Gordon Auto Body Parts Co., Ltd.				
Participant Address / 廠商地址:	No. 48, Neixi Road, Luzhu District, Taovuan City 338				
Applicable CAPA Certification Standard / 適用之CAPA認證標準:	<input checked="" type="checkbox"/> CAPA 101	<input type="checkbox"/> CAPA 201	<input type="checkbox"/> CAPA 301	<input type="checkbox"/> CAPA 501	<input type="checkbox"/> CAPA 601
Participant Part Number / 零件號碼:	FDRS15FL1				
Car Company Part Number / CCS 號碼:	CK4Z16006A	Partslink Number / 號碼:	FO1240294		
Part Description / 零件種類:	Fender L				
Application Description / 車種年份:	Ford Transit Cargo Van, 15-17				
	Ford Transit Passenger Van, 15-17				
Status Affects / 受影響狀態:	<input checked="" type="checkbox"/> Part Number / 零件編號	<input checked="" type="checkbox"/> Lot Number / 批號:	04/17A		

Status as of this Notice / 通知後狀態:

NEW PART APPROVAL

Reason for Status Change / 狀態變更原因:	<input type="checkbox"/> Participant Request / 廠商要求	<input type="checkbox"/> Production Inspection 產品檢驗	<input type="checkbox"/> CAR / 改善措施要求
<input type="checkbox"/> Random Material Testing 隨機抽樣材測	<input type="checkbox"/> MM VTF / 市場觀察合車	<input checked="" type="checkbox"/> Other / 其他:	

Describe / 原因: NPA – passed dimension test.

Seal Size: / 標籤尺寸:	<input checked="" type="checkbox"/> Standard / 標準	<input type="checkbox"/> Alternative / 替代選擇
--------------------	---	---

When a part number is decertified or deleted, in order to re-enter the CAPA Certification Program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval Fee.

註：當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。

Submitted By / 提案人:		Issued By / 簽發者:	
	CAPA Validator		CAPA Administrator