

NOTICE OF STATUS (PART NUMBER/PART LOT) CHANGE FORM

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:	26574				
Notification Date / 通知日期:	02/01/2016				
Participant Name / 廠商名稱:	Tong Yang Industry Co., Ltd				
Participant Address / 廠商地址:	No. 98, Sec. 2, An Ho Road, Annan District, Tainan 709				
Applicable CAPA Certification Standard / 適用之CAPA認證標準:	☐ CAPA 101	☒ CAPA 201	☐ CAPA 301	☐ CAPA 501	☐ CAPA 601
Participant Part Number / 零件號碼:	DS-04376BAQ				
Car Company Part Number / CCS 號碼:	850B21KA0A	Partslink Number / 號碼:	NI1115101		
Part Description / 零件種類:	Cover, Lower				
Application Description / 車種年份:	Nissan Juke S/SL/SV, 11-14				
Status Affects / 受影響狀態:	☒ Part Number / 零件編號	☒ Lot Number / 批號:	01/16A		

Status as of this Notice / 通知後狀態:

NEW PART APPROVAL

Reason for Status Change / 狀態變更原因:	☐ Participant Request / 廠商要求	☐ Production Inspection 產品檢驗	☐ CAR / 改善措施要求
☐ Random Material Testing 隨機抽樣材測	☐ MM VTF / 市場觀察合車	☒ Other / 其他:	

Describe / 原因: Passed all testing requirements

Seal Size: / 標籤尺寸:	☒ Standard / 標準	☐ Alternative / 替代選擇
--------------------	---	---

When a part number is decertified or deleted, in order to re-enter the CAPA Certification Program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval Fee.

註：當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。

Submitted By / 提案人:		Issued By / 簽發者:	
CAPA Validator		CAPA Administrator	