

NOTIFICATION OF CAPA (Part No. / Part Lot) STATUS CHANGE

CAPA 零件號碼 / 批號狀態變更通知

Notification Number / 通知單編號:		18457	
Notification Date / 通知日期:		11/06/2012	
Participant Name / 廠商名稱:		Gordon Auto Body Parts Co., Ltd.	
Participant Address / 廠商地址:		No. 48, Nie-Shi Road Lu Chu Hsiang Taoyuan County R.O.C., 338	
Applicable CAPA Certification Standard / 適用之CAPA認證標準:		☒ CAPA 101 ☐ CAPA 201 ☐ CAPA 301 ☐ CAPA 501 ☐ CAPA 201A ☐ CAPA 401	
Participant Part Number / 零件號碼:		FDF012FR1	
Car Company Part Number / CCS 號碼:		BM5Z16005A	Partslink Number / 號碼: FO1241287
Part Description / 零件種類:		Fender R	
Application Description / 車種年份:		Ford Focus, 12	
Status Affects / 受影響狀態:		☒ Part Number / 零件編號 ☒ Lot Number / 批號: 10/12A	
Status as of this Notice / 通知後狀		NEW PART APPROVAL	
Reason for Status Change / 狀態變更原因		☐ Participant Request / 廠商要求 ☐ Production Inspection 產品檢驗 ☐ CAR / 改善措施要求	
☐ Random Material Testing 隨機抽樣材測		☐ MM VTF / 市場觀察合車 ☒ Other / 其他:	
Describe / 原因: <u>NPA – passed dimension test.</u>			
Seal Size: / 標籤尺寸:		☒ Standard / 標準 ☐ Alternative / 替代選擇	
NOTE: When a part number is decertified or deleted, in order to re-enter the CAPA program, the Participant must register the part number using the New Part Registration Form and pay the applicable New Part Approval fee. 註：當整個零件號碼被取消認證或刪除時，如欲將該零件重新加入CAPA認證計畫，廠商必須送交新零件註冊登記表為零件重新註冊，並繳交新零件核可費用。			
Submitted By / 提案人:		Issued By / 簽發者:	
CAPA Validator		CAPA Administrator	