

Mercedes Vito 03-10 Original Vehicle Before Assessment



Mercedes Vito 03-10 Original Centre Grille



Mercedes Vito 03-10 TONG YANG Centre Grille



TYG Centre Grille L/H



Original Centre Grille L/H



Mercedes Vito 03-10



TYG Centre Grille R/H



Original Centre Grille R/H

Mercedes Vito 03-10

- No Faults Identified
- Comparative Fit Quality To Original
- VTF Judgement: **PASS**