



- Vehicle Fit Tested
- Production Surveyed

This is to certify that:

10011119
Bumper Front

Licence holder: S.P.M.P S.r.l
Manufacturer Code: 4AEAD9DB0023
Vehicle test fitted in: Europe
Fits to: Fiat Scudo 2006 L.C.V.

Part Image



Vehicle Image



Certified as having the following requirements successfully evaluated:

Vehicle Fit Tested, Production Surveyed

This certificate is only applicable for parts
which have the Thatcham TUV Certified Part label attached

Date Issued
15th October
2009

Expiry Date
October
2017

Peter Shaw
Chief Executive
Thatcham Research

Certificate No:
TTC0115

Boris Tuzza
TÜVRheinland
Italia S.r.l

Production Part Approval - Part Submission Warrant



| | | | | | |
|---|--------------|-------------------|---------------------------------------|------|--|
| Part Name / Parte di ricambio | Front bumper | Part No. / | 100 11119 | | |
| Checking Aid No. | 245 | OES Part No: | 1497581078 | Date | |
| Prime material used | PP | OE prime material | PP | | |
| Supplier Manufacturing Information | | | Certification Dept. Contact | | |
| Name: SPMP SRL | | | Carlo Pozzoli | | |
| Address: Via del Valà 20 20048 CARATE BRIANZA (MI) | | | Vehicle make, model & year | | |
| | | | FIAT SCUDO 2006 | | |

Reason For Submission

| | |
|---|--|
| <input checked="" type="checkbox"/> Initial Submission | <input type="checkbox"/> Change to optional construction or material |
| <input type="checkbox"/> Engineering Changes | <input type="checkbox"/> Sub Supplier or material source change |
| <input type="checkbox"/> Tooling: Transfer, replacement, refurbishment or additional; | <input type="checkbox"/> Change in Part Processing |
| <input type="checkbox"/> Correction of Discrepancy | <input type="checkbox"/> Parts produced at additional location |
| <input type="checkbox"/> Other – Please specify _____ | |

Submission Requirements (Please Check boxes)

| |
|--|
| <input checked="" type="checkbox"/> Warrant |
| <input type="checkbox"/> 2 Parts taken from a minimum stock run of 100 parts |
| <input type="checkbox"/> Material test results / Certificates |
| <input type="checkbox"/> Dimensional Results |
| <input type="text" value="8714468"/> Purchase Order Number |

Declaration

I affirm that the samples represented by this warrant are representative of our production parts and have been produced in compliance with the rules and guidelines of Thatcham/TUV Rheinland certification program as defined in TQAM. The materials used in the production of these parts have been tested in accordance with the programs material validation requirements.

I have noted any deviations from this declaration below.

Explanation /Comments:

| | | | | | |
|--|---|-----------------------------------|--------------------------------|-----------|--------------|
| Print Name: | Carlo Pozzoli | Title | Tech. Resp. | Phone No. | 0362 1785111 |
| Manufacturer Authorised Signature <i>Carlo Pozzoli</i> | | | | Date | 02/10/09 |
| FOR THATCHAM USE ONLY | | | | | |
| Part Disposition | <input checked="" type="checkbox"/> Submitted for Certification | <input type="checkbox"/> Rejected | <input type="checkbox"/> Other | | |
| Name | Ernesto Collino | Signature | | Date | |

| Ref | Revision | Date Issued | Owner | Page | | |
|-------------|----------|---------------|-----------|------|----|---|
| TQSD 013.31 | Issue 3 | November 2008 | D. Lander | 1 | of | 1 |


FIAT, Scudo 2006

SPMP Front Bumper
Compared To:
Original Front Bumper

Fiat, Scudo 2006 Original Vehicle Before Assessment



Fiat, Scudo 2006 Under Bonnet Cross Dimensional Measurement




"X" Measures a distance of: (1337)mm


"Y" Measures a distance of: (1337)mm

Vehicle Within Required Tolerance


Fiat, Scudo 2006 Original Front Bumper




Fiat, Scudo 2006 SPMP Front Bumper Fitted




Alternative Front Bumper L/H




Original Front Bumper L/H





Fiat, Scudo 2006





Alternative Front Bumper R/H



Original Front Bumper R/H



Fiat, Scudo 2006



Front grill



FIAT, Scudo 2006

- No Faults Identified
- Comparative Fit Quality To O.E.M
- VTF Judgement: **PASS**